

REMA Tip Top EPDM Hot Splice Material Curing Chart

The following cure times are for the
High Temperature Belt Splicing Materials curing at 320 Deg F.

Belt Thickness		Cure Time
mm	Inches	
9.5	3/8"	40 min.
11.1	7/16"	45 min.
12.7	1/2"	50 min.
14.2	9/16"	55 min.
15.8	5/8"	60 min.
17.4	11/16"	65 min.
19.0	3/4"	70 min.
20.6	13/16"	75 min.
22.2	7/8"	80 min.
23.8	15/16"	85 min.
25.4	1"	90 min.

